



NEW TECHNICAL BULLETIN

...THE CUSTOMERS CHOICE

Contact Us: www.listo-ltd.com

Software Updates

OP – V8.0Q

Released 27/10/11

TW – V2.C.6i

Released 06/01/12

Dear Customer,


Welcome to the Listo Ltd New Technical Bulletin.
The following *Software Update* is now available.



Software Update

TouchWin software – V2.C.6i

To Download the update please visit www.listo-ltd.com,
www.xinje-support-centre-listo.com or www.econ-sg.com.



LINKS

www.listo-ltd.com

www.xinje-support-centre-listo.com



The V2.C.6i version has been released in order to fix some known bugs which were affecting previous versions.

1. *Fix: when previously choosing ABB AC500 series, user was unable to download.*
2. *Fix: cannot open the MP project made by V2.99.*
3. *Fix: when the bar graph is horizontal, and if the pointer is 0 an error occurs.*
4. *Fix: in recipe download, the recipe data includes PLC objects.*
5. *Support TAIAN TP03 series PLC.*
6. *Fix: Modbus ASCII cannot read and write the register group.*
7. *Fix: fail to create the data library table.*
8. *Fix: "activate when the screen starts" function abnormal when the unit is public.*
9. *Fix: TG865 baud rate not correct.*
10. *Adjust CAD graph function.*
11. *Enlarge TH, TG keyboard size.*

Please consider the environment before printing this page

To pass on this product bulletin please click [here](#)

If you do not wish to receive further messages from Listo Ltd simply click [here](#)

Ref: TB0002-TW-V2-C-6i

If you have any ideas how we can improve our Bulletin or you would like any more information please do not hesitate in contacting us.